


FIG. 1A



10

A schematic diagram of a belt and pulley system. A continuous belt, labeled 30, is shown in a vertical loop. At the top of the loop is a circular pulley labeled 56, and at the bottom is another circular pulley labeled 58. Two rectangular components, labeled 52 and 50, are positioned on the left and right sides of the belt, respectively. Each rectangle contains a dashed line forming a U-shape, with the label 54 placed between the two rectangles. An arrow labeled 28 points upwards from the bottom left towards the belt.

Fig. 2A

Fig. 2B

--

Diagram illustrating a corner joint or connection. A line labeled 60 points to a corner. A line labeled 64 points to a vertical surface. A line labeled 62 points to a horizontal surface.

006260-15292960




Fig. 4